



Daily Update

April 24

Geological Work

Devil's Slide (post mile 39.14)

- Drilling operations resumed to install the second inclinometer. An inclinometer is the instrument that measures the rate at which the slide is moving.
- An on site meeting took place between Caltrans Geotechnical Engineers and Structural Designers. The purpose of the meeting was to assess actual site conditions and discuss design concepts for the repair.

Slide at Post Mile 39.77

- Caltrans engineers from the Office of Structures reviewed conditions at the site. Samples of material oozing from the hillside were taken for analysis.

Repair Work

Slide at Post Mile 40

- Repair work continued with the installation of drains and placement of rocks at the bottom of the excavated portion of the hillside.

